

AMENDMENT UNDER 37 C.F.R. § 1.111  
USSN 10/042,321  
Attorney Docket No. Q68046

**IN THE SPECIFICATION:**

**At page 8, please replace the first full paragraph with the following new paragraph:**

*A1*

Fig. 3 is a cross-sectional view taken along the line 3-3 A-A of Fig. 2.

**At page 8, please replace the third full paragraph with the following new**

**paragraph:**

*A2*

Fig. 5 is a cross-sectional view taken along the line 5-5 B-B of Fig. 4.

**At page 8, please replace the eighth full paragraph with the following new**

**paragraph:**

*A3*

Figs. 10A, 10B, and 10C are plan views Fig. 10 is a plan view showing related lamp  
sockets having wrong attachment prevention ribs.

**At page 9, please replace the first full paragraph with the following new paragraph:**

*A4*

Fig. 1 is an exploded, perspective view showing one preferred embodiment of the lamp  
socket of the invention, Fig. 1 is a perspective view of the lamp socket of Fig. 1, Fig. 3 is a cross-  
sectional view taken along the line 3-3 A-A of Fig. 2, Fig. 4 is a plan view of a wire connection

AMENDMENT UNDER 37 C.F.R. § 1.111  
USSN 10/042,321  
Attorney Docket No. Q68046

portion of fig. 2, Fig. 5 is a cross-sectional view taken along the line 5-5 ~~B-B~~ of Fig. 4, and Fig. 6  
is a plan view showing one preferred embodiment of the socket assembly of the invention.